GM 2014 YEAR-TO-DATE NORTH AMERICAN RECALLS INCLUDING EXPORTS

#	DATE	MY/MODELS	SUBJECT	U.S. POPULATION	GMNA & EXPORTS
1	1/13	2014 Chevrolet Silverado and GMC Sierra full-size pickups	Overheated Exhaust Components	325,213	378,131
2	1/23	2014 Chevrolet Trax/Tracker (Mexico and export only)	Fuel Line Quick Connector	0	2,069
3	2/20	2014 Buick Enclave, LaCrosse, Regal, and Verano; 2014 Chevrolet Cruze, Impala, Malibu and Traverse, GMC Acadia	Transmission Shift Cable Adjuster Body Fractures (NC)	355	388
4	2/25	2005-07 Chevrolet Cobalt; 2006-2007 Pontiac Pursuit; 2003-07 Saturn ION; 2006-07 Chevrolet HHR and Pontiac Solstice; 2007 Saturn Sky, Opel/Vauxhall GT, Daewoo G2X and Pontiac G5	Ignition Switch Torque Performance	1,367,146	1,620,665
5	3/17	2013-14 Cadillac XTS	Brake Vacuum Booster Pump Vent and Connector	63,903	66,218
6	3/17	2009-14 Chevrolet Express and GMC Savana	Front Passenger Airbag Performance (NC)	303,013	354,553
7	3/17	2008-13 Buick Enclave, Chevrolet Traverse, GMC Acadia, Saturn Outlook	Side Impact Airbag Connector	1,176,407	1,334,986
8	3/28	2014 Cadillac ELR	Electronic Brake Control Module Calibration	656	662
9	3/28	2008-11 Chevrolet HHR; 2008-10 Chevrolet Cobalt; 2008-10 Pontiac G5; 2008-10 Pontiac Solstice; 2008-10 Saturn Sky; 2008-10 Opel GT; 2008-09 Daewoo G2X	Ignition Switch Torque Performance	823,788	970,741
10	3/28	2013 and 2014 MY Chevrolet Cruze models equipped with 1.4L turbocharged engine (RPO LUV)	Half Shaft Fracture	174,046	197,327
11	3/28	2014-15 full-size trucks and full-size utilities with MYC transmission	Oil Cooler Fitting	489,936	559,249
12	3/31	2004-06 Chevrolet Malibu/Malibu Maxx, Pontiac G6; 2004-07 Saturn ION; 2008-09 Chevrolet Malibu, Pontiac G6, Saturn Aura; 2010 Cobalt; 2009-10 Chevrolet HHR; Previous EPS Recall Service Parts	Electronic Power Steering	1,352,729	1,522,744
13	4/9	2005-2010 Chevrolet Cobalt; 2006-2011 Chevrolet HHR; 2006-2010 Pontiac Solstice; 2003-2007 Saturn ION; 2007-2010 Saturn Sky and Pontiac G5	Ignition Cylinder	2,191,014	2,591,406
14	4/19	2009-2010 Pontiac Vibe	Air Bags (Toyota)	23,249	40,514
15	4/24	2013 Cadillac SRX	Hesitation	50,571	56,367
16	4/24	2015 Chevrolet Silverado HD and GMC Sierra HD	Diesel Transfer Pump	51	59
17	4/29	2014 Chevrolet Traverse, GMC Acadia and Buick Enclave	Inaccurate Fuel Gauge	51,640	57,131
18*	4/29	2007-2008 Saturn Aura	Shift Cable	56,214	59,627
	5/19	2004-2008 Chevrolet Malibu; 2005-2008 Pontiac G6	Shift Cable	1,074,932	1,215,791
19	5/7	2014 Chevrolet Malibu and Buick LaCrosse	Brake Rotors	8,208	8,590
20	5/13	2014 Chevrolet Malibu and Buick LaCrosse	Brake Boost (NC)	140,067	144,780
21	5/13	2014 Chevrolet Silverado and GMC Sierra Light Duty; 2015 Chevrolet Tahoe	Tie-rods	477	523
22	5/14	2005-2007 Chevrolet Corvette	Low Beams	103,158	111,889
23	5/14	2014 Cadillac CTS	Wipers	19,225	21,563
24	5/14	2004-2012 Chevrolet Malibu; 2004-2007 Malibu Maxx; 2005-2010 Pontiac G6; 2007-2010 Saturn Aura	Brake Lamps	2,440,524	2,703,657
25	5/16	2015 Cadillac Escalade	Passenger Air Bag (NC)	1,402	1,533
26	5/19	2009-2010 Saturn Outlook; 2009-2014 Chevrolet Traverse, GMC Acadia and Buick Enclave	Front Seat Belts	1,339,355	1,509,523
27	5/19	2015 Chevrolet Silverado HD and GMC Sierra HD	Loose Fuse Block	58	58
28	5/21	2004-2008 Chevrolet Aveo; 2005-2008 Pontiac Wave and G3	Daytime Running Lamps	217,454	284,699
29	5/21	2004-2008 Chevrolet Optra (Imported from GM Korea; sold in U.S. Territories)	Daytime Running Lamps	214	214
30	5/30	Certain 2014 Chevrolet Silverado and GMC Sierra; 2015 Chevrolet Tahoe and Suburban, GMC Yukon and Yukon XL and Cadillac Escalade and Escalade ESV	Sensing and Diagnostic Module	334	344
31	5/30	Certain 2014 Chevrolet Silverado LD; 2014 GMC Sierra LD; 2015 Chevrolet Silverado HD, Tahoe and Suburban and GMC Sierra HD, Yukon and Yukon XL	Base Radio Chime (NC)	57,512	69,552
32	5/30	Certain 2013 and 2014 Chevrolet Spark and 2013 Buick Encore	Passenger Air Bag	61	87
33	5/30	Certain 2012 Chevrolet Cruze, Camaro and Sonic and Buick Verano	Driver's Air Bag Shorting Bar	31,520	36,012
34	5/30	2014 Chevrolet Corvette	Sensing and Diagnostic Module	33	37
35	6/11	2004-2011 Saab 9-3 Convertible	Seat Belt Retractor	28,789	29,750
36	6/11	2012 Chevrolet Sonic	Transmission Turbine Shaft Fracture	21,567	24,904
37	6/11	2014 Buick LaCrosse	Driver's Door Wiring Splice (NC)	14,765	15,185

09-50026-mg Doc 13114-3 Filed 04/20/15 Entered 04/20/15 19:35:09 Exhibit 3 Pg 2 of 3

38	6/13	2010-2014 Chevrolet Camaro	Key FOB Can Bump Ignition	464,712	511,528
39	6/16	2005-2009 Buick Allure and LaCrosse; 2006-2014 Chevrolet Impala; 2000-2005 Cadillac Deville; 2004-2011 Cadillac DTS; 2006-2011 Buick Lucerne; 2006-2007 Chevrolet Monte Carlo	Key Replacement from Slot to Hole	3,140,725	3,340,555
40	6/16	2013-2014 Cadillac ATS and 2014 Cadillac CTS	Shift Cable	90,750	109,031
41	6/16	2015 Chevrolet Silverado 2500/3500 HD and GMC Sierra 2500/3500 HD	Steering Pump Clamp Inspection	124,527	141,260
42	6/16	2011 Cadillac AWD CTS	Gasket Leak	16,932	18,279
43	6/16	2014 Chevrolet Corvette with Competition Sport Seats	Air Bags	712	961
44	6/16	2014-2015 Chevrolet Silverado and GMC Sierra	Unsecured Floor Mats	184	184
45	6/27	2014-15 Chevrolet Silverado and GMC Sierra; 2015 Chevrolet Suburban and Tahoe, GMC Yukon and Yukon XL with 4WD	4WD Transfer Case	392,459	466,940
46	6/27	2013-14 Chevrolet Cruze	Driver Air Bag	29,019	33,085
47	6/27	2013-14 Chevrolet Caprice Police; 2014 Chevrolet SS	Windshield Wiper Module	4,794	4,794
48	6/27	2014 Chevrolet Corvettes with the FE1 or FE3 suspension	Rear Shock Weld	1,939	2,054
49	6/30	1997-2005 Chevrolet Malibu; 1998-2002 Oldsmobile Intrigue; 1999-2004 Oldsmobile Alero; 1999-2005 Pontiac Grand Am; 2000-2005 Chevrolet Impala and Monte Carlo; 2004-2008 Pontiac Grand Prix	Unintended Ignition Key Rotation	5,877,818	6,584,859
50	6/30	2003-2014 Cadillac CTS, 2004-2006 Cadillac SRX (2014 models are derivative models in previous generation body style; 2014 CTS sedan not involved)	Unintended Ignition Key Rotation	554,328	616,179
51	6/30	2011-2014 Chevrolet Cruze; 2012-2014 Chevrolet Sonic; 2013-2014 Chevrolet Trax, Buick Encore and Verano	Engine Block Heater Power Cord	2,990	20,134
52	6/30	2014 Chevrolet Camaro and Impala, Buick Regal, Cadillac XTS	"Superhold" Joint Fastener Torque	106	117
53	6/30	2007-11 Chevrolet Silverado HD, GMC Sierra HD equipped with an auxiliary battery	Auxiliary Battery Underhood Fusible Link	9,371	12,008
54	6/30	2005-2007 Buick Rainier, Chevrolet TrailBlazer, GMC Envoy, Isuzu Ascender, Saab 9-7x; 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL	Driver's Door Module for Power Locks and Window Switches	181,984	188,705
55	7/18	2014-2015 Chevrolet Spark	Lower Control Arm Ball Joint	1,919	3,065
56	7/21	2013 Chevrolet Malibu; 2011-2013 Buick Regal	Front Turn Signal Bulbs	120,426	127,235
57	7/22	2015 Chevrolet Tahoe and Suburban, GMC Yukon and Yukon XL	Roof Rail Air Bag	22	25
58	7/22	2014 Chevrolet Impala	Electronic Power Steering	57,242	65,276
59	7/22	2010-2012 Chevrolet Equinox, GMC Terrain and Cadillac SRX 2011-2012 Chevrolet Camaro, Buick Regal and LaCrosse	Power Height Adjustable Seats	414,333	475,161
60	7/22	2013-2014 Buick Encore and Cadillac ATS; 2014 Cadillac CTS and ELR, Chevrolet SS, Caprice, Caprice PPV and Silverado 1500 and GMC Sierra 1500; 2015 Chevrolet Silverado 2500/3500 HD and GMC Sierra 2500/3500 HD	Seat Hook Weld Incomplete	124,007	151,923
61	7/28	2007 Chevrolet Optra (Canada); 2009-2010 Chevrolet Aveo; 2009 Pontiac G3/Wave	Reduced Brake Performance	1,968	2,091
62	8/7	2013 Cadillac ATS, Chevrolet Trax (Canada) and Buick Encore (Imported)	Frontal Lapbelt Pretensioners	48,059	72,826
63	8/7	2002-2004 Saturn Vue	Ignition Key Pullout in Run Position	202,155	215,243
64	8/7	2013-2014 Cadillac ATS (Export Only)	Front Exterior Lighting (NC)	0	3,624
65	8/7	2014-2015 Chevrolet Impala	Console Bin Door Latch (NC)	14,940	15,386
66	8/13	2011-2014 Chevrolet Express and GMC Savana	CNG High Pressure Regulator Leak	3,196	3,209
67	8/20	2013-2014 Cadillac SRX; 2014 Chevrolet Impala	Sensing and Diagnostic Module	5	5
68	8/29	2011-2013 Chevrolet Caprice Police Patrol Vehicles	Transmission Selector Roll and Selector Pin Displacement (NC)	7,598	7,601
69	9/4	2004-2007 Cadillac CTS-V; 2006-2007 Cadillac STS-V	Overheating Fuel Pump Module	10,005	10,498
70	9/4	2008-2009 Pontiac G8; 2011-2013 Chevrolet Caprice	Unintended Ignition Key Rotation	47,225	50,094
71	9/4	2014 Chevrolet Sonic	Steering Column Electrical Connection	304	335
72	9/4	2013-2015 Cadillac XTS; 2014-2015 Chevrolet Impala	Emergency Brake Drag (NC)	205,309	221,558
73	9/17	2010-2015 Cadillac SRX; 2011-2012 Saab 9-4X	Rear Suspension Nut Torqueing	290,107	430,550
74	9/17	2014 Chevrolet Corvette	Driver's Air Bag Center Plate Fracture	89	94
75	9/17	2015 Chevrolet Corvette	Parking Brake Cable (NC)	783	809

09-50026-mg Doc 13114-3 Filed 04/20/15 Entered 04/20/15 19:35:09 Exhibit 3 Pg 3 of 3

76	9/23	2013-2015 Chevrolet Spark and Spark EV	Hood Latch Corrosion (NC)	89,294	93,834
77	10/1	2013-2014 Chevrolet Tahoe and Suburban, Cadillac CTS, Escalade and Escalade ESV, GMC Yukon and Yukon XL; 2014 Chevrolet Traverse, Express and Silverado HD, GMC Acadia, Savana and Sierra HD, and Buick Enclave	Chassis Control Module Contamination	106,307	126,418
78	10/7	2015 Cadillac Escalade	Passenger Air Bag Cover	1,046	1,154
79	10/9	2015 Chevrolet Colorado and GMC Canyon	Air Bag Wiring	2,283	2,432
80	11/25	2006-2009 Buick LaCrosse; 2006-2007 Chevrolet TrailBlazer, GMC Envoy and Buick Rainier; 2006 Chevrolet TrailBlazer EXT and GMC Envoy XL; 2006-2008 Saab 9-7X and Isuzu Ascender	Headlamp Driving Module Failure	273,182	316,357
81	12/17	2015 Cadillac SRX	Incorrect Seat Track Bracket	3,155	3,361
82	12/22	2015 Chevrolet Silverado and GMC Sierra	Insufficient Heat Treatment Rear Axle	152	167
83	12/22	2015 Chevrolet Silverado HD and GMC Sierra HD	Loose Hose Clamp	56	67
84	12/23	2011-2013 Cadillac Escalade, Escalade ESV and Escalade EXT, Chevrolet Avalanche, Silverado, Suburban and Tahoe, GMC Sierra, Yukon and Yukon XL	Ignition Binding	83,572	92,221
*Shift Cable is a single recall initiated 4/29 and expanded 5/19 *Totals on No. 49 adjusted downward on 7/23 due to double counting of some models (NC) = Noncompliance Recall					GMNA TOTAL 30,433,365